

ORIGINAL



0000042630

SALLQUIST, DRUMMOND & O'CONNOR, P.C.

ATTORNEYS AT LAW  
TEMPE OFFICE  
4500 S. LAKESHORE DRIVE  
SUITE 339  
TEMPE, ARIZONA 85282

RICHARD L. SALLQUIST

PHONE (480) 839-5202  
FACSIMILE (480) 345-0412  
E-MAIL [dick@sd-law.com](mailto:dick@sd-law.com)

February 10, 2006

Linda Jaress, Executive Consultant  
Arizona Corporation Commission  
Utilities Division  
1200 W. Washington  
Phoenix, AZ 85007

Re: Utility Source, L.L.C. Application for a Certificate of Convenience and Necessity Extension; Docket No. WS-04235A-05-0707; Insufficiency Response

Dear Linda:

The Commission Staff, through the Engineering Division, requested one additional item in addition to the information provided in our January 17, 2006 Insufficiency Response. That was the Arizona Department of Environment Equality Drinking Water Compliance Status Report.

Please find attached a copy of the February 7, 2006 CSR for the Bellemont Truck Center, Public Water System ID Number 03-300. Please note this designation was assigned by ADEQ when that system serve the commercial entity only and prior to formation of the utility company or granting of the Certificate of Convenience and Necessity. This is the only water system serving that area

In the event you have any questions regarding these matters, please do not hesitate to call.

Sincerely,

Richard L. Sallquist

Enclosures

cc: Docket Control (15 copies w/o attachments)  
Jian Liu (fax)  
Lonnie McCleve

RECEIVED  
2006 FEB 13 P 12:27  
AZ CORP COMMISSION  
DOCUMENT CONTROL

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Bellemont Truck Center

**Public Water System ID #:** 03-300

**Public Water System Type:** ☒ CO ☐ Non-transient Non-community ☐ Transient Non-community

**Overall Compliance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

**Monitoring and Reporting Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
Comments:

**Operation and Maintenance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: 8-5-04

**Administrative Orders:**

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

**System information:**

Number of Points of Entry 1 Number of Sources 2 Population Served 1500

Service Connections 15 Initial Monitoring Year 2006 Initial MAP Year 2006

**Evaluation completed by:** Jim Puckett

**Phone:** 602-771-4649 **Date:** 2-7-06

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.